


# Indian Island Cultural & Environmental Restoration Project


## Erosion Control



CCC Member Placing Oyster Shell-Filled Bags on Shell Mound, 2002




Illustrative Cross Section of Erosion Control on South Side of Project Site



Illustrative Cross Section of Erosion Control on North Side of Project Site



Deteriorated Temporary Erosion Control, Looking Southwest, 2002



View Northeast of Erosion Control on the Shell Mound, 2002